

**Lower Diversion Dam Cleaning Project
April 2005**

The lower diversion dam that feeds water to Ditch 1 and 2 had become somewhat clogged due to past floods and narrowing of the stream with sand banks, weeds, and debris. This was not allowing the water to flow into the head gates properly.



North Ditch One Head Gate



Center Ditch Two Head Gate



A track hoe was used to clean the area above the dam



Improved Flow to the Head Gates and Over the Dam