

OFFICERS REPORT for 2007
MOAB IRRIGATION COMPANY
Annual Meeting
January 21, 2008

This is the second year the new watering schedule by Zones has been in effect. For the most part it has had very few problems. There have been a few shareholders that haven't liked it, but the overall view is that it's working great. A few changes have been made to different zones for the coming year.

The board had a change of one of its members this year. Dennis Wacker resigned in April from President to spend more time with his wife traveling. The board would like to give a special thank to Dennis for his three plus years of excellent service to the company. His skills will be missed. Dennis recommended Ben Byrd to the board as his replacement. The board accepted Ben to temporarily fill Wacker's position. Ben Byrd and Dave Engleman will be up for election this year.

At the April meeting the water master also resigned his job. He said he would stay on if the board shortened his work hours and increased his salary. The board felt that the budget would not support the increase so the board accepted his resignation. The board members took over the responsibilities of the in town water master. The board has hired a water master for 2008 who will report for work in March. Board members are going to retain some duties to shorten the learning curve of the new water master.

An area of concern has been brought up this past summer was that of controlling the water on your property when you are taking water. In an attempt to NOT get into the situation of the board members becoming policemen, the board would encourage each shareholder to control their water so it does not become a nuance to the public or neighbors. The shareholder is responsible for where their water goes.

A pipe repair project on 5th West and Marcus Ct. was completed. A new valve was installed by the Grand County Credit Union, but leaks there continue to be a problem. This will be fixed by a permanent solution when the rest of 5th West is addressed. Fifth West has approximately six leaks that need to be repaired. The metal box at Williams Way & 100 West has a leak. The line that goes behind the old visitor center on North Hwy 191 has a few leaks that need to be repaired so the property owner can rent the property. Ditch three also has several areas that will need to be repaired.

The lower diversion dam has now become the top priority to be repaired due to the continued deterioration of the dam apron. Flooding that has occurred over the past several years severely added to the problem. The board is looking at bids and will start work when all the permits are in place. Thanks to George Carter and Ben Byrd for taking on this very large and important task.

At the last regular meeting in December the board approved a bid from a contractor to begin needed repairs on our system. As soon as all contracts are signed and any unexpected problems are solved, work will get started. The board will prioritize the jobs depending on the budget money.

With all the moisture received so far winter, we are looking for a good year for the irrigation company for 2008.