

Beavers

Occasionally beavers decided that our dams make a great place to set up home. But for some reason though, the water flowing through the diversion openings is just not acceptable to them. So they do their best to block off the water flow. One beaver in particular became quite the nuisance at the lower diversion dam. He was eventually trapped inside a sand chute and removed to a better home location.



The beaver was cutting down every tree around the diversion dam and using the branches to block the pipe openings. It was causing a lot of extra work for the water master.



It is not real obvious, but there is a beaver hiding up inside the channel to the sand chute.



These lucky guys crawled in after it. Lucky them.



Out came the beaver. They are transferring the critter to a different cage at this point.



One beaver – ready to be transported to a better location.